


CH 1:- Introduction.

* Diagram of Materials :-



* Type of materials :-

1)- Metals. Ex:- Al, Fe ...

2)- Ceramics Ex:- clay, Cement, glass.

3)- polymers Ex:- plastic, rubber.

4)- Composite Ex:- Wood.

↳ Composed of two individual materials

Metals Ceramics materials.


5)- Advanced Materials :- "Self Reading"

* Materials properties :-

Mechanical optical Thermal chemical electrical magnetic.

CH₂ :- Atomic structure .

* Bohr's atomic model :-



such that :-

$N \rightarrow$ neutrons [No charge]

$P \rightarrow$ protons [positive]

$e \rightarrow$ electrons [negative]

* A shell is where an electron be.

* Protons and neutrons are placed in the nucleus.

* Atomic Number = Number of protons
= Number of electrons.

* Atomic Mass = $n_p \times m_p + n_n \times m_n$

such that :- $n_p \rightarrow$ number of protons

$m_p \rightarrow$ mass of proton

$n_n \rightarrow$ number of neutrons


$m_n \rightarrow$ mass of neutron.

* Isotope :- atoms of the same element but different in it's number of neutrons.


* Atomic weight :- Weighted average of the atomic masses of the atom's naturally occurring isotopes. (g/mol).

* Electronegativity :- tendency to acquire electrons.

↳ Increases from left to right and
From bottom to top in the periodic table.



Bonding.



* Primary Bonds :-

1). Ionic Ex :- NaCl

- Involves electron transfer.
- Non-directional Bond.
- Occurs between high difference in electronegativity.
- A strong bond.

2). Metallic Ex :- Al-Al

- Strong bond
- Occurs between the atoms of same element.
- No secondary bond.
- Non directional bond.

3). Covalent

- Ex :- CH₄, H₂O ...
- No electrons transfer.
- directional bond
- Occurs in C, S, 4th group elements.

* Ionic character :-

$$IC = 1 - e^{-0.25 [X_A - X_B]} \times 100\%$$


$X_A, X_B \rightarrow$ Electronegativities of bond elements.

CH3 :- Crystalline Solids.

* Solidification:-

↳ Liquid $\xrightarrow[t_0]{\text{turns}}$ Solid.

* Crystal $\rightarrow$ atomic arrangement.



* Unit cell :- Small repeated entities.


↳ Building block of Atoms.

* Unit cell is defined using parameters:-

→ 3 edges lengths.

→ 3 interaxial angles

* Review table "3.2" :-



1)- Body centered Cubic :- spheric

- Type of Crystall diagram $\swarrow$ cubic

→ Coordination number = 8

↳ Number of boundary Atoms

→ Number of atoms per unit cell = 2

Face atoms + Corner atoms + Body atoms.

* Atomic packing Factor :-

→ What fraction of volume of the unit cell is occupied by atoms.

$$APF = \frac{\text{Volume of atoms}}{\text{Volume of UC}}$$

* Comparison :-

properties	BCC	FCC
Coordination Number	8	12
Number of Atoms	2	4
relation between Unit cell length (a) and Atomic radius (R).	$a = \frac{4R}{\sqrt{3}}$	$a = 2\sqrt{2} r$
APF	0.68	0.74.

* The Hexagonal Crystal structure :-

$$\begin{aligned} \rightarrow \text{Number of atoms} &= \text{body} + \text{Face} + \text{Corner} \\ &= 3 + \frac{1}{2} \cdot 2 + 2 \left(\frac{1}{6} \times 6 \right) \\ &= "6" \text{ atoms} \end{aligned}$$

$$\rightarrow \text{Coordination Number} \rightarrow "12"$$

$$\rightarrow \text{APF} \rightarrow "0.74"$$

$$\rightarrow \text{Example} \rightarrow "Mg"$$

* "HCP and FCC"

↳ "incommon in APF and Coordination Number."

* Polymorphism :-

↳ Changing in Crystal structure according to change in atmosphere "Temperature".

* Iron and Titanium are polymorphism Metals.

* Theoretical density :-

$$\rho = \frac{n \cdot A}{V_c \cdot N_A}$$

atoms/unit cell Atomic weight
Volume/unit cell Avogadro's number.


$$= \frac{\text{atoms} \cdot \frac{\text{g}}{\text{mol}}}{\text{cm}^3 \cdot \frac{\text{atom}}{\text{mol}}} = \frac{\text{g}}{\text{cm}^3}$$

Ex:- Copper has an atomic radius of 0.128 nm , an FCC crystal and an atomic weight of 63.5 g/mol , compute it's density.

$$\begin{aligned} \rho &= \frac{4 \times 63.5}{a^3 \times 6.02 \times 10^{23}} \\ &= 8.8 \text{ g/cm}^3. \end{aligned}$$

$$\begin{aligned} R &= 0.128 \text{ nm} \\ a &= 2\sqrt{2} \times 0.128 \\ &= \sqrt{\text{nm}} \\ &= \sqrt{10^{-7}} \text{ cm} \end{aligned}$$

- * Crystallographic points, directions, and planes :-
- * point position :-



Ex:- point 2 $\rightarrow (1, 1, 1)$.

- * Review slides for the progress to find directions.

- * Direction analysis :-
- Projection method :-

projections

projections (in terms of a, b, c)

Reduction

Enclosure

x	y	z
$\frac{1}{2}$	1	0
$a/2$	b	0
a	2b	0
[1, 2, 0]		

- difference between two points :-

$$\begin{aligned} \rightarrow 2(a/2, b, 0) - (0, 0, 0) &= [a, 2b, 0] \\ &= [1, 2, 0]. \end{aligned}$$

- * planes :-

$\rightarrow$ Three or more directions.

- IF the plane passes through origin we should

$\rightarrow$ shift the origin one unit cell.

$\rightarrow$ or shift the plane.


TIPS :-

* shift origin in the y-axis.

* shift origin so that the plane becomes before

* We define the intersection points with the new origin shifted.

	x	y	z
new	∞	-1	$\frac{1}{2}$
→	(0	-1	2)



* Review slide for example.

Miller Indices.

↳ Name of planar indices.

* Stacking Sequence

- FCC

↳ stacking sequence is repeated every three plane

↳ "ABC"

- HCP

↳ repeated every two planes

↳ "AB"

* Poly Crystals:-

↳ All Metals are poly Crystalline, more than 1 Crystal.

* Crystal Solidification :-

* Small crystals $\rightarrow$ growth $\rightarrow$ grains.

- grains $\rightarrow$ Face crystals

- ~~the~~ border of grains $\rightarrow$ appears on the microscope.

* Metals differ in Mechanical properties with ~~the~~ different directions.

$\rightarrow$ Anisotropy.

$\rightarrow$ ~~dir~~ directionality of properties.

- Isotropic Materials :-

$\rightarrow$ properties are independent of the direction.

* Microscopes ^{gives} $\rightarrow$ optical surface properties only.

* X-ray diffraction :-

$\rightarrow$ used to see lattice and depth of unit cells.

- Source of X-Ray

$\rightarrow$ Material

$\rightarrow$ diffraction

$\rightarrow$ analysis of structure.

* Scattering event :-

such as $\rightarrow$ atom, unit cell, direction, plane.

$\rightarrow$ where a x-ray diffracts.


$\rightarrow$ cause an increase of λ

$\rightarrow$ every two waves join together.

* Subtraction event :-

$\rightarrow$ No output.

$\rightarrow$ two waves at different direction cancel each others.



* $n\lambda = 2d_{hkc} \sin \theta$

* $d_{hkl} = \frac{a}{\sqrt{h^2 + k^2 + l^2}}$

* Suggested

3.14 / 3.71 3.31 / 3.32 / 3.41 / 3.42 / 3.62 / 3.65 / 3.66 / 3.64.

* Output graph :- / Diffraction pattern / :-

- x-axis $\rightarrow$ Diffraction angle (2θ).


- y-axis $\rightarrow$ Intensity (amplitude).

* at peaks $\rightarrow$ Diffraction happened.

* To know the Crystal structure using the graph:-

- BCC $\rightarrow h + k + l \rightarrow$ even

- FCC $\rightarrow h, k, l$, all of them
 $\begin{cases} \rightarrow \text{even} \\ \rightarrow \text{odd} \end{cases}$



* Linear and planar Densities :-

- Linear densities :- number of atoms centered on direction vector / length of direction vector. (LD).

- planar ~~of atom~~ Densities :- number of atoms centered on plane / Area of plane.

* Linear and planar densities are important in deformation.

* For cubic structures :-

- Miller Indices with same indices, but different order are parallel or within the same family of planes.

CH4 :- Imperfections in Solids.

* Solids

↳ Crystal Structure.

* Imperfections :-

↳ defects

↳ A lattice irregularity.

* alloy

↳ addition of two metals.

↳ better properties.

↳ enhance properties.

* Defects :-

↳ 1) point defects → (atom) → one or two

2) Linear defects → (direction) → one dimensional

3) Interfacial defects → (plane) → Two dimensional

4) Bulk defects → (lattice). Three dimensional.

* All crystal structures include defects.

1) point defects :-

a) Vacancies

↳ empty or vacuum atomic site.

b) Self-Interstitials :-

↳ an atom placed in the wrong atomic site.

* To define whether there is a defect or not we use "Equilibrium number of Vacancies" & activation energy

$$N_v = N \exp \left(- \frac{Q_v}{kT} \right)$$

atomic site Boltzmann's constant abs. temp.

* For most metals, $\frac{N_v}{N} = 10^{-4}$

↳ A vacancy every 10000 atomic site.

- Find N_v of in 1m^3 of Cu at 1000°C , given:-

$$\rho = 8.4 \frac{\text{g}}{\text{cm}^3}, A_{\text{Cu}} = 63.5 \frac{\text{g}}{\text{mol}}, Q_v = 0.9 \text{ eV/atom}$$

$$N_A = 6.02 \times 10^{23} \text{ atoms/mole}, k = 8.62 \times 10^{-5} \text{ eV/atom}\cdot\text{K}$$

$$N_v = 2.7 \times 10^{-4}$$

point defects

Vacancies

Self-interstitial

Impurities.


- existence of other metals in pure metal structure.

↳ (less than 1%)


* binary

↳ alloy of (2) metals.

* Impurities and alloying :-



- alloying $\rightarrow$ depends on solubility.



* In alloying we should reach the melting ~~as~~ point of the element with the bigger melting point.

- $X \rightarrow$ host material

- atoms of $y \rightarrow$ go to the vacancies of element x .

* Solubility might be in (solid state).

$\begin{cases} \rightarrow \text{Complete} \\ \rightarrow \text{partial} \\ \rightarrow \text{Unsoluble (rare).} \end{cases}$

* $Cd \rightarrow$ an element that is unsoluble
 $\rightarrow$ Can't make alloys.

* Solubility Effects:-

- 1- Crystal structures
- 2- atomic radius
- 3- Electronegativity.
- 4- Valance electrons.

* Solvent $\rightarrow$ host, higher concentration.

* Identification of Solubility :-

1) Same crystal structure "FCC with FCC" ---

2) Atomic radius approximately the same.

* Weight percent :- C = Composition.

First mass. $C_1 = \frac{m_1}{m_1 + m_2} * 100\%$, $C_i = \frac{m_i}{m_i + m_H + m_N + \dots}$

$$= \frac{m}{\text{total mass.}}$$

* 2) - Dislocations - Linear Defects :-

- Types :-

a) - Edge

b) - Screw

c) - Mixed.

* Burger Vector :- Distance between 2 - planes.

- Edge dislocation $\rightarrow$ Dislocation line and burger vector $\perp$

- Screw dislocation $\rightarrow$ Dislocation line and burger vector $\parallel$

3)- Interfacial defects :- (plane, Area).

- Types of planar defects :-

a)- External Surfaces :-

↳ where crystal structure terminates.

→ surface atoms are in high energy state.

↳ not bound to maximum No. of nearest neighbors.

↳ minimize surface area.

b)- Grain boundaries :-

↳ different crystallographic orientations.

↳ atomic mismatch.

- Types :- → High angle grain boundary.

→ Small (low)

↙ Tilt boundary

↘ Twist boundary.

↙ edge dislocation.

→ screw dislocation

* grain boundary are more chemically reactive than grains.

c)- Twin boundaries :-

↳ There is a specific mirror lattice symmetry.

↳ region of materials between is termed "Twins".

↳ results from mechanical shear force (displacement).

or annealing heat treatment.

4)- Bulk (volume) defects :-

Ex:- 1) - Cracks

2) - Pores

3) - Vibrations

4) -

self study

* Microscopy :- (self reading).

↳ "How to calculate grain size".

- optical microscope:-

↳ "grains"

Reflection. [✓]

→ We see "the reflections of the surface."

* Types :-

transmission. (X)

How To make the metal surface a mirror surface :-

1 - Cutting.

2 - grinding.

3 - polishing, etching. → diamond paste.

mirror surface. ↓ grain boundaries


CH 4. Suggested :-

4.3 - 4.4 - 4.20 - 4.18 - 4.23 - 4.31 - 4.25 - (4.32 - 4.33 - 4.34 - 4.35)

* grain size calculation :-

* magnification :-

↳ microscope effects.



Two ways → intercept. (mathematically).

→ AST (comparison).

↳ $n = 1, 2, 3, \dots \rightarrow$ (standard).

(microscope views)

- # Self reading #

* CH 6: Mechanical Behaviour *

Strength.

hardness.

- universal tensile testing machine
(UTM)


↳ Measures ultimate stress.

- UTM differs for materials :-

↳ load capacity.

* when testing, we should avoid sharp edges.

↳ stress concentration.




* UTM :-

- For cylinders

↳ V shape grips


for sheets

↳ Flat grips



* The load will increase until the necking happens.

* Example for data observed.




- define :-

sample :- mild steel


geometry / cylinder (πr^2)
/ flat (width $\times$ thickness).

gauge length
→ length of the sample after the cut



* Stress - strain Diagrams -

* load - elongation Diagram :-



* Cross head speed

→ change in load / time.

usually small


G_y = yield stress.

G_u = ultimate stress.

* Stress = $\frac{F}{A_{original}} = \frac{N}{mm^2} = Mpa$

* Strain = $\frac{DL}{L_0}$ → dimensionless.

- Diagram :-



- Elastic region → linear part of the diagram (0 to G_y).

- plastic region → non linear

- stiffness → modulus of elasticity.

- resilience →

- toughness →

yield point → end of elastic region

ultimate point → start of failure.

* Elastic Region :-

- Turn on $\rightarrow$ yield
- Small stress $\leftrightarrow$ small strain
- stress and strain $\rightarrow$ proportional (linear).

$$y = ax + b^{\text{zero}}$$


$$\sigma = a \epsilon \rightarrow \sigma = E \epsilon$$

modulus of Elasticity.

$$E = \text{slope} = \tan \theta = \frac{\Delta \sigma}{\Delta \epsilon} \rightarrow \text{Mpa}$$

$\downarrow$
stiffness

more elastic $\rightarrow$ bigger (E).



* Elastic Region :-

- Turn on $\rightarrow$ yield

① Small stress $\Leftrightarrow$ small strain

② stress and strain $\rightarrow$ proportional (linear).

$$y = ax + b^{\text{zero}}$$

$$\sigma = a \epsilon \rightarrow \sigma = E \epsilon$$

modulus of Elasticity.

$$E = \text{slope} = \tan \theta = \frac{\Delta \sigma}{\Delta \epsilon} \rightarrow \text{Mpa}$$

$\downarrow$
stiffness

more elastic $\rightarrow$ ~~smaller~~ ^{smaller} (E).

- Hook's law $\rightarrow \sigma = E \epsilon$

- less stiffness $\rightarrow$ closer to polymers.

* Cylinder, $x = l_0$, area = πr^2

$$\epsilon_{\text{area}} = \frac{\Delta \text{area}}{A_0} = \frac{\Delta d}{d_0}$$

* Sheet x, y, z ,

$$\epsilon_{\text{length}} = \frac{\Delta L}{L_0}, \quad \epsilon_{\text{width}} = \frac{\Delta W}{W_0}, \quad \epsilon_{\text{thick}} = \frac{\Delta t}{t_0}$$

③ In the elastic region, upon removing load, the sample returns to its original dimensions.


$E \gg \sigma_{\text{yield}} \rightarrow$ always.

④ area under elastic ~~region~~ ^{region} = modulus of resilience.
 $= \frac{1}{2} \epsilon_y \sigma_y$

* to find yield stress, offset Method.

* Poisson's ratio (ν) = $\frac{\epsilon_L}{\epsilon_a}$ → change in dimensions relative to each other

* plastic Region :-



* Modulus of toughness

↳ Energy absorbed under the whole curve. (per unit volume).


↳ Area under the whole curve. (Mpa) (N/mm²).

* ductility :- (Function of strain).

↳ The bigger the strain, ~~the bigger~~ more ductile is the material.

$$= \text{elongation percent} = \frac{l_f - l_0}{l_0} \times 100\%$$

$$= \text{Areal reduction} = \frac{A_f - A_0}{A_0} \times 100\%$$



- True Stress :-

↳ Considering area change.

$$\sigma_t = \frac{F}{A_c}$$

Engineering Stress

$$\frac{F}{A_0}$$

- True strain

$$= \ln \frac{l_c}{l_0}$$

Engineering strain

$$\frac{L - L_0}{L_0}$$

* $l_c = l_0 + \Delta L$ at any point.

* Volume is constant :-

$$A_0 L_0 = A_c L_c$$

* Mechanical behavior:-

$$\sigma_T = K \epsilon_T^n$$

True stress True strain

K :- strength coefficient

n :- strain hardening index.
↳ indication to

$$\sigma_T = \sigma_e (1 + \epsilon_e)$$

$$\epsilon_T = \ln(1 + \epsilon_e)$$

* hardness :-

↳ surface deformation (indents)

↳ ability of material to cut another.

↳ ability of the material to resist scratching.



- Thickness of the material is function to the
↳ indentation diameter
↳ " depth

$$t_h = 10 \times I \cdot \text{depth}$$

* Indention Tests:-

1) Brinell $\xrightarrow{\text{shape}}$ ball $\rightarrow$ Ceramics

2) Vickers $\xrightarrow{\text{shape}}$ pyramid $\rightarrow$ diamond.

3) Rockwell $\xrightarrow{\text{shape}}$ Cone / steel $\rightarrow$ Sphere / diamond.

- Difference between Rockwell C, B, A

↳ Load Scale.


CH 9 :- phase Diagram :-

Ex :- water + Salt.

- Solubility $\rightarrow$ depends on - temperature
- Solid solution.

Max. solubility

(x, y)
 $\swarrow \searrow$
Composition Temp.



- Component $\rightarrow$ water + Sugar.

- phases
 - $\rightarrow$ liquid $\rightarrow$ component $\rightarrow$ water
 - $\rightarrow$ solid $\rightarrow$ sugar.
 - $\rightarrow$ liquid + solid.

* Purpose



$\rightarrow$ What is the effect of adding a metal to another on the melting point or solidification point.

* phase diagram :-

- effect of adding a metal to another on the melting point (solidification point).

- Keywords :: Solubility limit. (max sol) $\rightarrow$ (Comp, temp).
(s.l.). (min sol)

Case	liquid	Solid	Resultant. Phase diagram
①	Complete.	Complete.	Isomorphous
②	"	partial.	partial
③	"	insoluble.	eutectic.



let X melting point be 800°C

For $X \rightarrow$
 $L = 700$
 $S = 500$
 -400
 $\rightarrow$ melting point (solidification point).

* Solubility in liquid state is
 $\rightarrow$ Turn the Furnace off to the temp. of the ~~max~~ biggest melting temp.
 $\rightarrow$ always complete.


* phase diagrams differ as a result of solubility Types.

* Isomorphous phase diagram :-

ex :- Ni $\rightarrow$ same C.S. $\rightarrow$ nearby atomic radiuses $\rightarrow$ Complete solubility.
 Cu melting point of Ni $\rightarrow 1450^\circ\text{C}$
 " " Cu $\rightarrow 1085^\circ\text{C}$

* To Find Temp. $\uparrow$ we use "Thermo Couple".

* When Solidification starts
 $\rightarrow$ Temp. is held constant for a long time relative to before solidification start.
 $\rightarrow$ cooling rate = $\frac{\Delta T}{\Delta t}$



* When the cooling rate decrease
 $\rightarrow$ solidification beginning.

- point A $\rightarrow$ Solidification begins.
 - point B $\rightarrow$ Solidification Ends.


* adding more Ni to Cu

↳ //Cu Melting point increases//
 $1085^{\circ} \rightarrow \approx 1400^{\circ} * (T_2) *$

* adding more Cu to Ni

↳ Ni Melting point decreases.

$1450^{\circ} \rightarrow \approx 1100 * (T_1) *$



given a Composition :- 80% Ni at 1500°C

- 1)- what is the phase present?
- 2)- phase Composition?
- 3)- phase amount?
- 4)- Microstructure?
- 5)- at what temp. the alloy will begin to solidify? which element solidify first?
- 6)- at what Temp. the alloy is completely solid?

* Isomorphous phase diagram.

↳ Same graph for all materials (Standard).

↳ Liquid state solubility is widened along the curve (Complete solubility).

↳ Solid state is widened along the curve (Complete solubility).

* When it is 100% of a metal, it is denoted (Metal) is the phase diagram.

* Phase amount $\rightarrow$ [weight Liquid + weight solid = 100%]
 $\rightarrow$ weight percent of the Liquid or solid.


* To draw micro structure in

1)- draw a circle

2)- label liquid.

3)- add solid grains.

4)- grains.



at 60% Ni
at 1150°C :-

1) Solid

2) $C_s = C_\alpha = 40\% \text{ Ni}$
 $60\% \text{ Cu}$


3) $W_s = 100\%$

4) same

5) 1280°C

6) 1220°C

Isomorphous
phase diagram
Composition (at% Ni)



at 60% Ni
 $T = 1310^\circ \text{C}$

1) Solid + Liquid (L + α)

2) $C_L = 64\% \text{ Ni}$
 $C_\alpha = 51\% \text{ Ni}$

3)

4)

5) 1350

6)

- at 40% Ni, 1500°C

q_1 :- What is the phase present?
Liquid

q_2 :- phase composition?
 $C_L \rightarrow 40\% \text{ Ni}$
 $60\% \text{ Cu}$

q_3 :- phase amount?
 $W_L = 100\%$
 $W_S = 0\%$

q_4 :- microstructure?
Liquid $\rightarrow$ (SS) liquid $\rightarrow$ solid.

q_5 :- At what temp. the alloy will begin to solidify?
1280°C / Nickel will solidify first.

q_6 :- At what temp. the alloy will be completely solid?
1220°C.

* The metal with the highest original solidification point, starts solidification first.

* The "thermo couple" Temp. will stay constant at two points :-
 ↳ Where each metal starts to solidify.

* The Greek letters " α, β, δ "
 ↳ Refers to solid solution Composition.

* When the point is in the $(L + \alpha)$ region :-

↳ ① Draw the tie line.

↓
 intersects with Liquidus line and α line.

↓
 projection to the composition axis.

②. phase amount :- (Lever Rule).

$$W_{\alpha} + W_L = 100\% \quad (1)$$

$$W_{\alpha} C_{\alpha} + W_L C_L = C_0 \rightarrow \text{given composition.}$$

↳ Solve for W_{α}, W_L

$$W_{\alpha} = \frac{C_0 - C_L}{C_{\alpha} - C_L}$$

$$W_L = \frac{C_{\alpha} - C_0}{C_{\alpha} - C_L}$$

From, the Tie line :-

$$R = C_0 - C_L$$


$$S = C_{\alpha} - C_0$$

$$R + S = C_{\alpha} - C_L$$

$$W_{\alpha} = \frac{R}{R+S}$$

$$W_L = 100 - W_{\alpha}$$

$$\text{or } W_L = \frac{S}{R+S}$$



* Partial phase diagram:-

- ↳ solid state isn't wide all over the diagram.
- Liquid state is wide.

↓ ↓

Partial Solubility.

↳ partial diagram:

* Def :-

α :- solid solution rich in pb

↳ solute :- Sn
solvent :- pb.

- max. solubility of Sn in pb :-
18.3 % Sn at 183°C

β :- solid solution rich in Sn.

↳ solute :- pb
solvent :- Sn


- max solubility of pb in Sn :-
2.2 % at 183°C.

* maximum solubility is ~~not~~ happens at the same temp.


* Solidification is complete at the temp. of the maximum solubility.

* When $T_1 = T_2 \rightarrow$ eutectic composition.


* eutectic reaction :-



not




* - Sn, Pb eutectic reaction



* eutectic alloy structure is



→



"Lamellar Layers"

* Any composition less than eutectic composition
↳ hypo-eutectic

* Any " more " " "
↳ hyper-eutectic.

partial phase diagram

- Take: 50% Sn, Just below
eutectic temp.
 ²
phase → ($\alpha + \beta$) / solids.

phase composition -

$$C_{\beta} = 97.8 \% \text{ Sn}$$

③ - weigh of phase

$$w_\alpha + w_\beta = 1$$

lever (rule) :-

$$W_{\alpha} = \frac{S}{R_{\alpha S}} = \frac{97.8 - 50}{97.8 - 18.3}$$

$$w_{\phi} = \frac{R}{R+s}$$


$$w_F = 1 - w_A.$$

④ - at what temp. the alloy will begin to solidify, which element will solidify first?

first?
220°C, Pb.

Microstructure.

6) - at what temp.
the alloy will be
completely solid?
 183°C .



* eutectic point :-
↳ transformation from liquid to two solids.
 $L \rightarrow \delta + Fe_3C$ at $1147^\circ C$, $4.3\% C$

* Eutectoid :-
↳ transformation from solid to two solids.



- hypo eutectoid
↳ C ($0 - 0.76\% C$)


- hyper eutectoid
↳ C ($0.76 - 2.14\% C$)

- the material at the eutectoid is :- pearlite.

* Steel
↓
 $Fe + C$
0.0 --- 2.14%
* low carbon steel
* high " "
* Medium carbon steel
0.022 → 0.76 " hypo eutectoid.
0.76 ← hyper eutectoid.

ech
Family

* Iron - Carbon phase diagram :-



↓
Steel.

Fe - C (0 - 2.14) = Steel.

* Increasing the composition of C more than (2.14%)

↳ Cast Iron → Brittle

- Increasing Comp. of C → more than 6.7%

↳ Graphite. "not important".

* We stopped at the composition of 6.7% C :-

1)- Fe₃C (compound) is

2)- Increasing the Comp. will start to form Graphite.

* From the diagram :-

α → Solid Solution rich in Fe (400 - 912) (Ferrite).

↓ solute → C
solvent → Fe

↳ Crystal structure of α → BCC.

* Maximum sol. of C in Fe :-

0.022 % C at 727°C

γ → Solid Solution rich in Fe (912 - 1400) (Austenite).

↓ solute C
solvent Fe


↳ max. sol. → 2.14 % C at 1147°C


- Iron (γ) → "Orange"

- Austenite → FCC (Increases solubility).

* Iron change its properties when the environment change. (Allotropy).

δ → 1400 - 1538 (BCC)






* 0.5% C Just below the eutectoid :-

1) - phase present ?
 $\alpha + \text{Fe}_3\text{C}$

2) - phase composition ?
 by tie line $\rightarrow C_\alpha = 0.022\% \text{ C}$
 $C_{\text{Fe}_3\text{C}} = 6.7\% \text{ C}$

3) - phase amount ?

$$W_\alpha = \frac{S}{P+S}, \quad W_{\text{Fe}_3\text{C}} = \frac{P}{P+S}$$




4) - phase amount of pearlite ?

$$M = C_0 - C_\alpha$$

$$N = C_{\text{pearlite}} - C_0$$

$$W_p = \frac{M}{N+M} = 6.5\%$$




* eutectic point :-

↳ transformation from liquid to two solids.
 $L \rightarrow \delta + Fe_3C$ at $1147^\circ C$, $4.3\% C$

* Eutectoid :-

↳ transformation from solid to two solids.



- hypoeutectoid

↳ C ($0 - 0.76\%$)

- hypereutectoid

↳ C ($0.76 - 2.14\%$)

- The material at the eutectoid is :- pearlite.

* Steel

↓

$Fe + C$

$0.0 \dots 2.14\%$

* low carbon steel

* high " "

* Medium carbon steel

$0.022 \rightarrow 0.76$ " hypoeutectoid.

$0.76 \leftarrow$ hyper eutectoid.